

RECALL NOTICE



SpeeCo, Inc.

**SpeeCo, Inc. announces a voluntary recall
of Fence Wire Stretchers**

**(Model numbers: S16111500, S161115TSC and S16112000) sold since
April 1, 2015.**



Models S16111500 and S161115TSC



Model S16112000

HAZARD: Wire under tension in the Fence Wire Stretcher can come loose and recoil. If this occurs, it can strike the operator or bystander and cause an abrasion or a contusion.

Consumer should immediately stop using the fence stretcher and return them to SpeeCo or the place of purchase for a full refund.

For more information:

855-271-7189

specofencestretcherrecall@blount.com

Monday through Friday, 8am-5:30pm Central Time

**This recall is being conducted in cooperation with the
U.S. Consumer Products Safety Commission**

Post until 12/1/2016